16-Feb- 2022 Meeting Minutes

CVA-MUL-AR-MOM-00004

### Location:

### **Teams Meeting**

## Meeting Attendees:

Dan Chicoyne (CNLOPB)
Sherry Rex (CNLOPB)
Will Jacobs (Cougar Helicopters)
Zach Dalley (Equinor-Operator Rep)
Mike Whittle (Suncor -Operator Rep-Chair)
Justin Meaney (Searose Workforce Rep)
Dave Hancock (ExxonMobil Operator Rep, Co-Chair)
Karl Holmes (Husky energy Operator Rep - Administrator)
Robert Normore (CNSOPB)
Craig Williams (Terra Nova FPSO- Workforce Rep)

#### Absent:

Paul Carter (Cougar Helicopters) ExxonMobil workforce representatives

Introduction of Newest HOSC member, Dave Hancock.

## Safety Moment

Will Jacobs

#### Importance of Safety Moments and Committees such as the HOSC

Discussed the importance with a focus on The Ocean Ranger, CGR 491 and the recent sinking of a Spanish fishing trawler, the Villa de Pitanxo

- safety moments thrive when there is a personal attachment to Lessons- Learned.
- many Lessons-Learned through Ocean Ranger & Cougar 491 have been shared across the global offshore community.
- In the roles that we have, we want to be seen as Good Safety Leaders.
- Is it worth the effort? if you are doing it right you may never find out.

#### **Previous Minutes Items**

Reviewed No comments

16-Feb- 2022 Meeting Minutes

CVA-MUL-AR-MOM-00004

### Aviation safety alerts and awareness

- CHI (Cougar Helicopters) Customer Flight Notifications
  - o 1 CFN related to heater hose. CFN- YYT-000225
    - Occurred after takeoff from HIB. Crew elected to return to HIB
    - Similar to CFN- YYT-000224 which occurred after takeoff from YYT
    - Same aircraft DKN
  - Operator has been replacing hoses since previous.
  - There are some supply chain issues with availablity
  - Operator does not regard this as a safety of flight issue.
    - However, at any time when there is a smell or haze it will not be ignored.
- Info Shares (CHI)
  - S-92A Ruptured Heater Hose CHI Info Share SQF-023
    - Updated information following a repeat occurrence
    - Added 2 new items to the infoshare
      - Questions were posed by the workforce and responses provided in the Infoshare
      - 2. Emergency Response procedures. Alert levels
        - These are published, CHI crews and onshore support are well versed with regards to the levels.
          - Crews judgment will not be questioned.
            - OCC, Dedicated SAR and Emergency response center for CHI (response center take the questions and communication items to alleviate the task load for the front line)
      - 3. The infoshare was well received by offshore workforce

**ACTION**: CHI brief HOSC on the process for SAR at upcoming meeting.

## Offshore Helicopter Safety Inquiry (OHSI) review

Conducted reviews of

- OHSI Recommendation 5
  - Worker Familiarization review of current video required to determine current applicability and value
- OHSI Recommendation 6
  - Personal Accountability further review required
- OHSI Recommendation 7
  - o Communication of Incident Reports, etc.
  - Ongoing HOSC item

**ACTION:** Review process with HOSC subgroup

16-Feb- 2022 Meeting Minutes

CVA-MUL-AR-MOM-00004

#### COVID-19

#### COVID-19

- Discussed current process at Heliport
  - Started in March 750 days ago
  - Was fairly stable early on
  - Now with new variant there are changes often once a week and several times a week
  - Cooperation and good discipline, planning and communication are effective.
  - Testing going on at the heliport, hotel, covid protocol transfer of flights, ways to decontaminate aircraft and suits
- Operator Specific
  - o Cenovus, rapid testing prior to flight, PCR testing, rapid testing days 3-5
  - ExxonMobil PCR testing, rapid testing days
    - Have dedicated 2 flights a week for presumptive positives.
    - Have some trailers back at the heliport now
      - to assist with testing, flights held pending weather, or coming back from a covid transfer gives them an opportunity to DOF suit etc.
  - o 3<sup>rd</sup> party will come in to decontaminate the trailers.
- In addition to individual or joint operator processes CHI must continue to follow Transport Canada requirements

## Extended flight day

- Parked for now. No change
- Slides were created for HIB from the worker's side
- Still interest from workers on Hebron
- Cenovus and Suncor workplace reps have no workforce updates
- The has not been engaged to move forward as of this meeting
- It remains with the Operators to discuss next steps, and CNLOPB engagement.
  - Doesn't not require all operators at the same time, however it would be best if they come together as a group

#### Class D fire extinguishers

- To manage a combustible metal fire
- Item brought to attention by the CNLOPB
  - Safety officers are sending this out their operator contacts
- Some installations have them onboard
- There was committee agreement that there should be a standard. Do we need it or do we not need it?
- Discussion held with the Helicopter OEM, Sikorsky
  - o There is support for the Class D
- CHI has had communication with one operator on how the requirement could be formed
- This is not a CAP437 item. This is above and beyond.

Action: Discuss among group to determine if this is an item that HOSC will make a recommendation

16-Feb- 2022 Meeting Minutes

CVA-MUL-AR-MOM-00004

## **HOSC Committee membership**

- Membership update
  - Vacant positions filled
    - Administrator Karl Holmes & Co-Chair Dave Hancock
  - ExxonMobil Workplace representatives required

Next meeting 11-May-2022 09:30 NL

Teleconference +1 647-749-9252 Canada, Toronto (Toll) (833) 829-4003 Canada (Toll-free) Conference ID: 823 894 210#